

Details

TEST	TEST METHOD	MINIMUM REQUIREMENT	
ADHESION	5970		20
TEAR	5134	Warp Fill	30 30
FLAME RETARDANCE	5903	2.0 sec-6.0"Char	
4" TENSILE	5100	Warp Fill	140 125
1" BEFORE ABRASION TENSILE	5102	Warp Fill	85 75
1" AFTER ABRASION TENSILE	5304	Warp Fill	60 60
COLD TEMPERATURE RESISTANCE	5874		-40
WEIGHT (oz/yd ²)	5041		12.0-14.0
HYDROSTATIC (PSI)	5512		200
WIDTH			+1/4" - 1/8"

METHODS NUMBERS REFER TO FEDERAL STANDARD #191-A TEXTILE TEST METHODS.